


COMPONENTI KIT ANTERIORE	FRONT KIT COMPONENTS	COMPOSANTS KIT ANTERIEURE	COMPONENTES KIT DELANTERO	G.P.L. L.P.G.	METANO C.N.G.
Riduttore	Converter	Vaporisateur	Reductor	LE/LSE	LME
Commutatore	Petrol start switch	Commutateur	Conmutador	C97-L / P97	
avviamento a benzina		demarrage essence	arranque a gasolina		
Lambda Ecologic System	Lambda Ecologic System	Lambda Ecologic System	Lambda Ecologic System	LES 95 o 98	
Elettrovalvola G.P.L.	LPG solenoid valve	Electrovanne GPL	Electroválvula GLP	EV2	-
Sensore manometro metano	CNG sensor and manometer	Capteur pression Methane	Sensor de GNC y manómetro -		805i
Miscelatore	Mixer	Melangeur	Mezclador	-	-
Emulatore staccainiettori	Injectors simulator	Emulateur injecteurs	Simulador de inyectores	Dedra (450)	
Variatore d'anticipo	Timing advance	Variateur d'avance	Variador de avance	Spark Master (540)	

SCHEMA ELETTRICO - WIRING DIAGRAM - SCHEMA ELECTRIQUE - SCHEMA ELECTRICO



NOTE

- Sonda Lambda a 4 fili. Segnale sul filo nero.
- Segnale T.P.S. sul filo centrale, rosso-nero.
- Fissare la massa del L.E.S. sul polo negativo della batteria.
- Scollegare la batteria prima di effettuare qualsiasi operazione.
- Saldare le connessioni elettriche.
- Non utilizzare rubacorrente
- MATERIALE CONSIGLIATO
- Set tubazioni e raccorderie

NOTES

- 4 wires Oxigen sensor. Signal is on the black wire.
- T.P.S. signal is on central wire, red-black.
- Connect L.E.S. ground to the battery negative pole.
- Disconnect the battery before working.
- Soft solder wiring connections.
- Do not use fast-connections
- OTHER SUGGESTED MATERIAL
- Pipes and fitting set

NOTES

- Sonda lambda à 4 fils. Signal sur fil noir.
- Signal TPS sur fil centrale, rouge-noir.
- Fixer la masse du LES sur le pôle négatif de la batterie.
- Déconnecter la batterie avant d'effectuer n'importe quelle opération.
- Souder les connexions électriques.
- Ne pas utiliser de connexions rapides.
- MATERIEL CONSEILLE
- Kit tuyaux et raccords

NOTAS

- Sonda Lambda con 4 cables. Señal en el cable negro.
- Señal T.P.S. en el cable central, rojo-negro.
- Fijar la masa del LES en el polo negativo de la batería.
- Desconectar la batería antes de efectuar cualquier operación
- Soldar las conexiones eléctricas
- No utilizar conexiones rápidas
- MATERIAL ADICIONAL
- ACONSEJADO
- Set cañerías y racores